1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5-63 EDITIONS	MFG. 9-66
	Approved For Release 2002/06/405/CIA PATE SECRET	UTING 9 10 10 10 10 10 10 10 10 10 10 10 10 10
	3 4	11 12
	TO : AOUTING 5 OX C	13 14 15
	FROM CHICK	16
	ACTIONS IN THE OPE	
	answers a getra	etem
	ECITION DE CONTROL CON	<u> </u>
	SECRET 270653Z CITE	ден ден жан бай жан ба Жан бай жан ба
5X1A		25X1A
	OXCART MAT	
5X1A	REF	

- 1. IT APPEARS THAT THE RAIN REMOVAL SOLUTION WAS CONTAMINATED OR THERE WAS INSUFFICIENT RAIN TO MAKE IT REACT PROPERLY.
- 2. WE CHECKED THE SYSTEM ON THE GROUND AND FOUND THAT IT WAS SLOW TO CLEAR. WE DRAINED AND PURGED THE SYSTEM AND REFILLED. IT THEN WORKED NORMALLY WHICH POINTS TO POSSIBLE CONTAMINATION. THERE IS NO SHELF LIFE LIMITATION ON THE FLUID.
- 3. PROPER ACTION OF THE RAIN REMOVAL FLUID REQUIRES CONSIDERABLE RAIN. IT IS POSSIBLE THAT IN THIS CASE, AFTER BREAKING OUT UNDER THE CLOUDS, THERE WAS NOT ENOUGH RAIN FOR THE FAST ACTION DESIRED. THIS ASPECT WILL BE DISCUSSED WITH THE PILOTS.
- 4. THERE IS NO REAL PROBLEM AND NO ASSISTANCE IS REQUIRED.

 SECRET TOR: 270658Z OCT 67

SECRET

GROUP 1 EXCLUDED FROM AUTO-MATIC DEVERGADING AND DECLASSIFICATION

5